

# Hollander Interchange Release 77.02

## WHAT'S NEW?

Hollander Interchange release 77.02 includes the following exciting new features:

- [Updated part coverage for 96 new models](#)
- [Front End images \(Part Type 100\) updated for 2011](#)
- [Numerous enhancements based on 422 IAR contributions](#)

## Updated Part Coverage for 96 New Models

Hollander Interchange release 77.02 now provides coverage for the following 96 new models.

<b>Audi</b> <ul style="list-style-type: none"><li>- A6</li><li>- A7 (2012)</li><li>- A8 (2011 - 2012)</li><li>- R8 (2011 - 2012)</li><li>- S6</li></ul>	<b>General Motors cont...</b> <ul style="list-style-type: none"><li>- 1500</li><li>- Chevrolet Suburban 1500</li><li>- Chevrolet Suburban 2500</li><li>- Chevrolet Tahoe</li><li>- GMC Sierra 1500</li><li>- Sierra Denali 1500</li><li>- Sierra Denali 2500</li><li>- GMC Terrain</li><li>- GMC Yukon</li><li>- GMC Yukon XL 1500</li><li>- GMC Yukon XL 2500</li></ul>	<b>Mazda</b> <ul style="list-style-type: none"><li>- CX-7</li><li>- CX-9</li><li>- 6</li><li>- RX8</li><li>- Miata/MX5</li><li>- Tribute</li></ul>
<b>BMW</b> <ul style="list-style-type: none"><li>- 128i</li><li>- 135i</li><li>- 323i</li><li>- 528i</li><li>- 535i</li><li>- 535i GT</li><li>- 550i</li><li>- 550i GT</li><li>- M1</li></ul>	<b>Honda</b> <ul style="list-style-type: none"><li>- Accord</li><li>- Crosstour</li><li>- Element</li></ul>	<b>Mercedes Benz</b> <ul style="list-style-type: none"><li>- GLK Class (GLK350)</li><li>- ML Class (incl ML63, ML350, ML450, ML550)</li><li>- R Class (R350)</li><li>- SLK (incl SLK63, SLK300, SLK350)</li></ul>
<b>Chrysler</b> <ul style="list-style-type: none"><li>- Chrysler 200</li><li>- Chrysler Town &amp; Country</li><li>- Dodge Avenger</li><li>- Dodge Caliber</li><li>- Dodge Caravan</li><li>- Dodge Dakota</li><li>- Dodge Durango</li></ul>	<b>Hyundai</b> <ul style="list-style-type: none"><li>- Accent</li></ul>	<b>Nissan</b> <ul style="list-style-type: none"><li>- 370Z</li><li>- GTR (2011 - 2012)</li><li>- Pathfinder</li><li>- Rogue</li><li>- Versa</li><li>- Xterra</li></ul>
<b>Ford</b> <ul style="list-style-type: none"><li>- Edge</li><li>- Flex</li><li>- Taurus</li><li>- Lincoln MKS</li><li>- Lincoln MKT</li><li>- Lincoln MKX</li></ul>	<b>Infiniti</b> <ul style="list-style-type: none"><li>- FX35</li><li>- FX50</li><li>- G25</li></ul>	<b>Porsche</b> <ul style="list-style-type: none"><li>- 911</li><li>- Boxster</li><li>- Cayman</li></ul>
<b>General Motors</b> <ul style="list-style-type: none"><li>- Buick LaCrosse</li><li>- Cadillac DTS</li><li>- Chevrolet Camaro</li><li>- Chevrolet Corvette</li><li>- Chevrolet Cruze</li><li>- Chevrolet Silverado</li></ul>	<b>Jeep</b> <ul style="list-style-type: none"><li>- Compass</li><li>- Patriot</li></ul>	<b>Rover</b> <ul style="list-style-type: none"><li>- Land Rover LR2</li><li>- Land Rover LR4</li><li>- Range Rover</li><li>- Range Rover Sport</li></ul>
	<b>Lexus</b> <ul style="list-style-type: none"><li>- CT200H (2011)</li><li>- IS F (2010 - 2011)</li><li>- IS250 (2010 - 2011)</li><li>- IS350 (2010 - 2011)</li><li>- LS460 (2011)</li><li>- LS600HL (2010 - 2011)</li><li>- LX570 (2010 - 2011)</li><li>- RX350 (2010 - 2011)</li><li>- RX450H (2010 - 2011)</li><li>- SC430 (2010)</li></ul>	<b>Saab</b> <ul style="list-style-type: none"><li>- 9-5</li></ul>

## Front End Images (PT 100) updated for 2011

Interchange coverage and the Hollander stock image set have been updated through 2011 for Front Ends. With this release, over 600 new images have been added.

## IAR Contributions Make a Difference!

Your voice matters! Here are a few examples of how everyone benefits from each other's contributions. We implemented 219 changes to the data and 69 additional notes and IDENTs. For more information, see "Interchange Action Requests (IARs)".

- From Concord, CA, for the Headlight (PT 114) on the Dodge Dakota for years 2005 through 2007, the index listing has been updated to allow you to define whether or not there is a "dome over bulb".

Dodge Dakota ('05 – 07)	
114 - Headlight	
2005 – 06	
R., w/dome over bulb .....	114-851B
w/o. dome over bulb.....	114-851A
L., w/dome over bulb .....	114-852B
w/o. dome over bulb .....	114-852A
2007	
R., (w/o dome) .....	114-851A
L., (w/o dome) .....	114-851B

- From Seattle, WA, for an Alternator on the 1997 Mercedes E320, after physical comparison of Hollander Interchange numbers 601-58727 and 601-58502, it was determined that the parts were identical.  
As a result, 601-58727 has been remarked (combined) into 601-58502.
- From Lebanon, PA, the notes for the Right Dash Air Bag (253-00395) on a Ford Focus, model years 2005 – 2007, have been rewritten to indicate that the cover can be sold separately and is available in multiple colors.  
*Module only: cover is sold separately and is available in multiple colors.*
- From Garretson, SD, the computer module for a 2002 Nissan Maxima (ID# A56-T09-ZK5) has been added to the notes for Hollander Interchange number 590-59284B.

## INTERCHANGE ACTION REQUESTS (IARs)

IARs are contributions submitted by our clients to improve the Hollander Interchange, request new part type coverage, report errors and/or omissions, and point out software and/or display issues. In this release, we processed approximately 450 Interchange Action Requests (IAR's); 215 implemented changes to the data, with another 70 providing additional Notes and Ident's.

### Submitting IARs

IARs can be submitted via an online form, phone, or fax. We will respond to your request within five business days of receipt.

Online: <https://www.training.audatex.us/IAR/>

Phone: (800) 825-0644 Ext. 3413 or (763) 519-3413

Fax: (763) 553-0270

## **AIR BAG WARNING**

### **Regarding any and all parts related to the function of the air bag restraint**

Original Equipment Manufacturers warn that by installing a used part from another vehicle, or even a new part other than specified by the manufacturer, the Air Bag or Supplemental Inflatable Restraint (SIR) or Supplemental Restraint System (SRS) may not perform as designed. Although parts look alike, they may function differently. Each system is tuned to that particular vehicle. Therefore, the vehicle manufacturers recommend never to use Air Bag or SIR or SRS components from another vehicle and never attempt to repair any Air Bag or SIR or SRS component. Service is intended to be replacement with new parts only.